

## FINAL INSPECTION REPORT Under the *Retirement Homes Act, 2010*

Inspection Information		
Date of Inspection: March 1, 2018	Name of Inspector: Michele Davidson	
Inspection Type: Routine Inspection		
Licensee: Amica Mature Lifestyles Inc. / Style de Vie Amica Inc. / 20 Queen Street, Toronto, ON M5H 3R4 (the "Licensee")		
Retirement Home: Amica at Whitby / 200 Kenneth Hobbs Avenue, Whitby, ON L1R 0G6 (the "home")		
Licence Number: T0146		

#### **Purpose of Inspection**

The RHRA conducts routine inspections as set out in section 77(3) of the *Retirement Homes Act, 2010* (the "RHA").

### NON-COMPLIANCE

1. The Licensee failed to comply with O. Reg. 166/11, s. 24; Emergency plan, general.

Specifically, the Licensee failed to comply with the following subsection(s):

**<u>24. (4)</u>** The licensee shall keep current all arrangements with community agencies, partner facilities and resources that will be involved in responding to an emergency.

#### Inspection Finding

At the time of the inspection, agreements with partners who would assist in emergency situations had not been renewed.

#### Outcome

The Licensee submitted plan to achieve compliance by March 31, 2018. RHRA to confirm compliance by inspection.



# NOTICE

The Final Inspection Report is being provided to the Licensee, the Registrar of the Retirement Homes Regulatory Authority (the "RHRA") and the home's Residents' Council, if any.

Section 55 of the RHA requires that the Final Inspection Report be posted in the home in a conspicuous and easily accessible location. In addition, the Licensee must ensure that copies of every Final Inspection Report from the previous two (2) years are made available in the Home, in an easily accessible location.

The Registrar's copy of the Final Inspection Report, as it appears here, will be included on the RHRA Public Register, available online at <u>http://rhra.ca/en/register/</u>

Signature of Inspector	Date
AT. Dande	March 22, 2018